






Todo








Verkar inte finnas ngnstans
Verkar inte finnas ngnstans


Sheet: /x37 dma/
File: x37dma.kicad_sch


Title:


Size: A3 Date: KiCad E.D.A. kicad 6.0.7-f9a2dced07-116-ubuntu22.04.1


Rev:
Id: 5/39







































































Sheet: /x37 sasi interface 2/
File: x37_sasi_interface_2.kicad_sch

Title:

Size: A3


Date:


Rev:


KiCad E.D.A. kicad 6.0.7-f9a2dced07-116-ubuntu22.04.1

Id: 30/39


kar inte finnas ngnstans på schemat










Sheet: /x37 connector 2/ File: x37_connector_2.kicad_sch		
Title:		
Size: A3	Date:	Rev:
KiCad E.D.A. kicad 6.0.7-f9a2dced07-116-ubuntu22.04.1		Id: 34/39










Sheet: /x37 power ic2/ File: x37_power_ic2.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. kicad 6.0.7-f9a2dced07-116-ubuntu22.04.1		Id: 38/39



Sheet: /x37 fix for check/ File: x37_fix_for_check.kicad_sch		
Title:		
Size: A4	Date:	Rev:
KiCad E.D.A. kicad 6.0.7-f9a2dced07-116-ubuntu22.04.1		Id: 39/39